USB2can Issues with one car	
Escrito por crowek123 - 22/06/2018 08:02	

Hello,

I'm having issues sniffing the CAN BUS on a 2017 Skoda, the device is returning all the same data, I tested it on a 2013 kia and it worked perfectly! I have the correct OBD cable and detailed on the forum as previously no data was being returned. Is it possible that the can bus is hidden from the OBD port on the skoda? I've tried bitrates of 500k, 250k, and 125k all with the same results. Any ideas/suggestions on what I could do differently?

Any help will be apprecited.

I didn't find the right solution from the Internet.

References:

https://www.8devices.com/community/viewtopic.php?f=16&t=1091 Whiteboard Video Production Service

Thank you.